

C0383 Rear Side Door Window Regulator Replacement - Left Side

Effective Date: Jul 1, 2012

LABOR CODE: C0383

Base	LABOR TIME:	0.6
------	-------------	-----