

E8061 Steering Linkage Outer Tie Rod Replacement - Left Side

Effective Date: Jul 1, 2012

LABOR CODE: E8061

Base

LABOR TIME:

0.6