

N6624 Occupant Safety Wiring and/or Connector Repair or Replacement

Effective Date: Jul 1, 2012

LABOR CODE: N6624

Includes: Diagnosis time to locate wire or connector condition and any associated fuse replacement.

Includes: SIR, safety belts, passive infrared release (PIR).

Note: This operation is only used for wiring and connector repairs without component replacement. Additional time to gain access or repair time greater than 0.5 hours must be submitted as Other Labor Hours and requires service manager approval. Diagnosis that results in a component replacement should use the component labor operation only.

Base	LABOR TIME:	0.1-0.5
------	--------------------	---------