

E4181 Insulator And/Or Support, Rear Stabilizer Shaft - Left - Replace

Effective Date: Jul 1, 2012

LABOR CODE: E4181

Base	LABOR TIME:	0.4
------	-------------	-----