

# E7692 Sensor Assembly, Steering Wheel Speed - Replace

Effective Date: Jul 1, 2012

LABOR CODE: E7692

Base

LABOR TIME:

0.3