


Windshield Side Garnish Molding Replacement



Callout	Component Name
<p>Preliminary Procedures</p> <p>Disable the SIR system, if equipped. Refer to SIR Disabling and Enabling .</p>	
1	<p>Windshield Side Garnish Molding Assembly</p> <p>Procedure</p> <ol style="list-style-type: none">1. Tabs must be installed prior to retainers.2. Tabs to be fully seated in the instrument panel (I/P) trim panel retainer and valance panel.3. Disconnect the electrical connectors.4. Ensure the tether is reattached when installed.