

D1832 Air Inlet Valve and Inside Air Valve Control Cam Replacement

Effective Date: Jul 1, 2012

LABOR CODE: D1832

RPO LHD	LABOR TIME:	0.3
RPO RHD	LABOR TIME:	0.4