

# R5154 Navigation Signal Splitter Replacement

Effective Date: Jul 1, 2012

LABOR CODE: R5154

Base

LABOR TIME:

0.4