

# B4359 Front Side Door Inside Handle Cable Replacement

Effective Date: Jul 1, 2012

LABOR CODE: B4359

Base

LABOR TIME:

0.5