

# C7340 Passenger Seat Cushion Heater Replacement

Effective Date: Jul 1, 2012

LABOR CODE: C7340

|      |             |     |
|------|-------------|-----|
| Base | LABOR TIME: | 0.7 |
|------|-------------|-----|

|  |           |         |
|--|-----------|---------|
| Diagnosis Time: You may claim up to the allowable labor hours depending on actual time performing diagnosis. | ADD TIME: | 0.0-0.3 |
|--|-----------|---------|