

C9032 Front Seat Belt Anchor Plate Tensioner Replacement

Effective Date: Jul 1, 2012

LABOR CODE: C9032

Base	LABOR TIME:	0.3
Diagnosis Time: You may claim up to the allowable labor hours depending on actual time performing diagnosis.	ADD TIME:	0.0-0.4
To Deploy Pyrotechnic Device	ADD TIME:	0.2