



D1832 Air Inlet Valve and Inside Air Valve Control Cam Replacement

Effective Date: Jul 1, 2012

LABOR CODE: D1832

RPO LHD

LABOR TIME: 0.3

RPO RHD

LABOR TIME: 0.4

