

B0613 Rear Bumper Fascia Inner Guide Replacement

Effective Date: Jul 1, 2012

LABOR CODE: B0613

Base

LABOR TIME:

0.6