

C8823 Inflatable Restraint Side Impact Sensor Replacement

Effective Date: Jul 1, 2012

LABOR CODE: C8823

Base	LABOR TIME:	0.4
------	-------------	-----

Diagnosis Time: You may claim up to the allowable labor hours depending on actual time performing diagnosis.	ADD TIME:	0.0-0.3
--	-----------	---------