

# B4310 Front Side Door Latch Replacement

Effective Date: Jul 1, 2012

LABOR CODE: B4310

Base

LABOR TIME:

0.7