

R0247 Radio Antenna Coil Replacement - Ground Side

Effective Date: Jul 1, 2012

LABOR CODE: R0247

Base

LABOR TIME:0.4

Diagnosis Time: You may claim up to the allowable labor hours depending on actual time performing diagnosis.

ADD TIME:0.0-0.3