


## Front End Upper Tie Bar Replacement



| Callout   | Component Name   |
|---|--|
| <p><b>Preliminary Procedure</b></p> <ol style="list-style-type: none"><li>1. Remove the front bumper fascia. Refer to <a href="#">Front Bumper Fascia Replacement</a></li><li>2. Remove the radiator support bracket. Refer to <a href="#">Radiator Support Bracket Replacement</a></li><li>3. Remove the radiator grille reinforcement support. Refer to <a href="#">Radiator Grille Reinforcement Support Replacement</a></li><li>4. Remove the hood primary and secondary latch. Refer to <a href="#">Hood Primary and Secondary Latch Replacement</a></li></ol> |  |
| 1   | Headlamp and Front Bumper Fascia Mount Panel Bolt (Qty: 4)<br><b>Caution:</b> Refer to <a href="#">Fastener Caution</a> in the Preface section.<br><b>Tighten</b><br>22 N·m (17 lb ft) |
| 2   | Front End Upper Tie Bar  |