

B9625 Front Side Turn Signal Lamp Replacement

LABOR CODE: B9625

Effective Date: Jul 1, 2012

Base	LABOR TIME:	0.2
------	-------------	-----