

# D1810 Air Inlet Valve Actuator Replacement

Effective Date: Jul 1, 2012

LABOR CODE: D1810

Base

LABOR TIME:0.8

Diagnosis Time: You may claim up to the allowable labor hours depending on actual time performing diagnosis.

ADD TIME:0.0-0.3