

B4180 Front Side Door Lock Cylinder Replacement

Effective Date: Jul 1, 2012

LABOR CODE: B4180

Includes: Cylinder coding.

Base

LABOR TIME:0.2

Diagnosis Time: You may claim up to the allowable labor hours depending on actual time performing diagnosis.

ADD TIME:0.3