

# D1212 Inside Air Temperature Sensor Replacement

Effective Date: Jul 1, 2012

LABOR CODE: D1212

RPO LHD

LABOR TIME: 0.2

RPO RHD

LABOR TIME: 0.3

Diagnosis Time: You may claim up to the allowable labor hours depending on actual time performing diagnosis.

ADD TIME: 0.0-0.3