

B4159 Outside Rearview Mirror Inner Actuator Replacement

Effective Date: Jul 1, 2012

LABOR CODE: B4159

Base	LABOR TIME:	0.5
Diagnosis Time: You may claim up to the allowable labor hours depending on actual time performing diagnosis.	ADD TIME:	0.0-0.3