

# B0612 Rear Bumper Fascia Guide Replacement

LABOR CODE: B0612		Effective Date: Jul 1, 2012	
Base		LABOR TIME:	0.6