

B4727 Rear Side Door Inside Handle Cable Replacement

Effective Date: Jul 1, 2012

LABOR CODE: B4727

Base

LABOR TIME:

0.7